

Picture 1(a): Business items displayed on pavement/sidewalk



Picture 1(b): Business items removed, sidewalk now open for pedestrians



Picture 2(a): Unsightly vacant building used by vagrants



Picture 2(b): Building being demolished



Picture 3(a): Vagrants and refuse under Albany bridge



Picture 3(b): Vagrants and refuse being removed



Picture 4(a): Open drain



Picture 4(b): Drain covered



Picture 5(a): Area flooded by burst water pipe



Picture 5(b): Repairing water pipe



Picture 6(a): No wheelchair access at Sassa office



Picture 6(b): New access ramp built at entrance of Sassa office



Picture 7(a): Damaged streetlight pole



Picture 7(b): Streetlight pole replaced



Picture 8(a): Pothole



Picture 8(b): Pothole repaired



Picture 9(a): Fallen / bumped traffic light pole



Picture 9(b): Traffic light pole secured with cement



Picture 10(a): Stray animals in neighbourhoods



Picture 10(b): Meeting with cattle owners to find a solution to this huge problem of roaming stray animals



Picture 11(a): Illegal dumping of refuse



Picture 11(b): Area cleaned



Picture 12(a): Sewer leakage



Picture 12(b): Drain blockage cleared

